



Einschraubfräser 90° / AP.. 10
Screw on type 90° / AP.. 10



Abmessungen [mm] Dimensions [mm]							Artikelbezeichnung Item Code	Bestell-Nr. Order No	Verfüg. Availability	Ersatzteile Spare parts	
D _C	d ₁	L	h	a _p	M	z					
16	12,7	23	41	9	M8	2	HMS90 AP10.016 Z02-M8	2256100	•	Spann- schraube Fastening screw HKE17-36166 5004300 MA = 2Nm	Torx- Schlüssel Torque wrench IP8 5000800
20	17,7	30	50	9	M10	3	HMS90 AP10.020 Z03-M10	2256200	•		
25	20,7	35	57	9	M12	4	HMS90 AP10.025 Z04-M12	2256300	•		
32	28,7	43	67	9	M16	5	HMS90 AP10.032 Z05-M16	2256400	•		

Aufsteckfräser 90° / AP.. 10
Face milling cutter 90° / AP.. 10



Abmessungen [mm] Dimensions [mm]							Artikelbezeichnung Item Code	Bestell-Nr. Order No	Verfüg. Availability	Ersatzteile Spare parts	
D _C	d _A	d ₁	h	ap/90°	z	Anzahl WSP Pieces Insert					
40	16	35	50	37	3	12	HMFH90 AP10.040 Z03-037	2245000	=	Spann- schraube Fastening screw HKE17- 36166 5004300 MA = 2Nm	Torx- Schlüssel Torque wrench IP8 5000800
40	16	35	50	37	5	20	HMFH90 AP10.040 Z05-037	2245100	=		
50	22	48	60	46	3	15	HMFH90 AP10.050 Z03-046	2245200	=		
50	22	48	60	46	5	25	HMFH90 AP10.050 Z05-046	2245300	=		
63	27	53	60	46	4	20	HMFH90 AP10.063 Z04-046	2245400	=		
63	27	53	60	46	7	35	HMFH90 AP10.063 Z07-046	2245500	=		