



Item Code	Stock		Dimension mm							Spare Parts				
	R	L	D	D min	F	L1	L2	λF	YP	Insert	Shim	Screw	Screw	Torx
HEI.1306100	•	•	8	10	6	100	30	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306200	•	•	8	10	6	100	30	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306300	•	•	8	11	6	100	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306400	•	•	8	11	6	100	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306500	•	•	10	13	7	125	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306600	•	•	10	13	7	125	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306700	•	•	8	11	6	100	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306800	•	•	8	11	6	100	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1306900	•	•	12	16	9	150	30	-8	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1307000	•	•	12	16	9	150	30	-8	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1307100	•	•	16	20	11	180	35	-8	0	CC.T 0602..	-	-	M2,5X7	T08
HEI.1307200	•	•	16	20	11	180	35	-8	0	CC.T 0602..	-	-	M2,5X7	T08
HEI.1307300	•	◦	16	20	11	180	35	-8	0	CC.T 09T3..	-	-	M3.5X8	T15
HEI.1307400	•	•	16	20	11	180	35	-8	0	CC.T 09T3..	-	-	M3.5X8	T15
HEI.1307500	•	•	20	25	13	200	40	-8	0	CC.T 09T3..	-	-	M3.5X11	T15
HEI.1307600	•	◦	20	25	13	200	40	-8	0	CC.T 09T3..	-	-	M3.5X11	T15
HEI.1307700	•	•	25	32	17	250	50	-8	0	CC.T 09T3..	-	-	M3.5X11	T15
HEI.1307800	•	◦	32	40	23	300	60	-8	0	CC.T 09T3..	-	-	M3.5X6	T15
HEI.1307900	•	•	25	32	17	250	50	-8	0	CC.T 1204..	CC..012	M6XM4	M3.5X11	T20
HEI.1308000	•	◦	25	32	17	250	50	-8	0	CC.T 1204..	CC..012	M6XM4	M3.5X11	T20
HEI.1308100	•	•	32	40	23	300	60	-8	0	CC.T 1204..	CC..012	M6XM4	M3.5X11	T20
HEI.1308200	•	•	40	50	27	400	70	-8	0	CC.T 1204..	CC..012	M6XM4	M3.5X11	T20
HEI.1606600	•	•	12	12.5	7	125	25	-10	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1606700	•	◦	16	15.5	9	150	30	-8	0	CC.T 0602..	-	-	M2,5X5	T08
HEI.1606800	•	◦	16	15.5	9	150	30	-8	0	CC.T 09T3..	-	-	M3.5X6	T15